

ARIZONA FORENSIC BREATH ALCOHOL
ANALYTICAL REPORT

Intoxilyzer - Alcohol Analyzer
Model 9000

SN: 90-004605
Test Date: 07/05/2025 Test Time: 23:25

Location:

INSTRUMENT INFORMATION

Analytical Instrument: INTOXYLYZER 9000
Serial Number: 90-004605
Software Version: 9439.01.00
Analytical Report Number: 46050705250549
QAS: MIYAZATO, KORY
QAS Permit #: 30215
Agency: GOODYEAR PD
Last 31-Day Check: 05/29/2025
Last Annual Maintenance: 06/16/2025

Software Version: 9439.01.00

Standard Lot #: 302-402972207
Standard Value: 0.100
Expiration Date: 02/20/2026
Bottle #: 19
Last Changed By: MIYAZATO, KORY
Permit #: 30215

SUBJECT INFORMATION

Test Date: 07/05/2025
Name: 31-Day Check,
Driver's License #:
Weight:
Gender:
State of Issue:
Date of Birth:
Driver's License Expiration:
Age:
Deprivation Start Time: 22:35
15-Minute Deprivation: Yes

Operator: MIYAZATO, KORY
Permit #:30215
Agency: GOODYEAR PD

Test	g/210L	Time
Air Blank	0.000	23:25:36
Calibration Chk	0.098	23:25:58
Air Blank	0.000	23:26:37

No RFI Detected

OPERATOR INFORMATION

Name: MIYAZATO, KORY
Agency: GOODYEAR PD
Permit #: 30215

STANDARD INFORMATION

Standard Value: 0.100
Standard Lot #: 302-402972207
Expiration Date: 2/20/2026
Bottle #: 19
Last Changed By:
MIYAZATO, KORY
Permit #: 30215

Test	g/210L	Time
Air Blank	0.000	22:55:58
Diagnostic Test	PASS	22:56:34
Air Blank	0.000	22:57:11
Calibration Chk	0.097	22:57:32
Air Blank	0.000	22:58:12
Subject Test 1	DEF*	23:01:24
Air Blank	0.000	23:02:07
Air Blank	0.000	23:02:47
Subject Test 2	0.000	23:03:03
Air Blank	0.000	23:03:44
Wait		23:07:47
Air Blank	0.000	23:08:24
Subject Test 3	INV**	23:08:44
Air Blank	RFI***	23:09:13

*Deficient Sample
**Invalid Sample - Begin new deprivation period
***RFI Detect

Not a Successfully Completed Test Sequence

RESULTS

EXCEPTION MESSAGES

* Deficient Sample
** Invalid Sample - Begin new deprivation period
*** RFI Detect
All air blank results must be 0.000.
Consecutive subject test results must not differ
by more than 0.020 g/210L.
Standard check results must be ±10%.

EXHIBIT I-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY
INTOXILYZER MODEL 9000

PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST K. M. YAZDANI 1139 AGENCY GOODYEAR
DATE 7/5/25 TIME 2255
INTOXILYZER SERIAL # 90-004605

- ☒ 1. Ensure that gas tank is attached and contains a standard alcohol concentration .100 AC

DIAGNOSTIC TESTS

- ☒ 1. Clock time check
☒ 2. Date check

OPERATIONAL TESTS

- ☒ 1. Deficient Subject Test (Proper Sample Recognition)
Deficient Sample printed
☒ 2. Alcohol-free Subject Test (Proper Sample Recognition):
0.00 AC
☒ 3. Mouth Alcohol Subject Test (Proper Sample Recognition):
Invalid Sample – Begin new deprivation period printed
☒ 4. Radio Frequency Interference Test (Error Recognition):
RFI Detect printed
☒ 5. Standard Calibration Check:
0.098 AC
☒ 6. Air Blanks Completed
☒ 7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES ☒ NO ☐

COMMENTS:

SIGNATURE

K. M. YAZDANI 1139

Intoxilyzer - Alcohol Analyzer
Model 9000

SN: 90-004605

Test Date: 07/22/2025

Location:

Test Time: 20:42

Software Version: 9439.01.00

Standard Lot #: 28424100A1

Standard Value: 0.100

Expiration Date: 11/05/2026

Bottle #: 024

Last Changed By: MIYAZATO, KORY

Permit #: 30215

Operator: MIYAZATO, KORY

Permit #: 30215

Agency: GOODYEAR PD

Test	g/210L	Time
Air Blank	0.000	20:42:48
Calibration Chk	0.103	20:43:10
Air Blank	0.000	20:43:49

No RFI Detected